
### Living Streets Community Street Audit Report

Aberfeldy March 2018



We are Living Streets Scotland, part of the UK charity for everyday walking. We want to create a walking nation where people of all generations enjoy the benefits that this simple act brings, on streets fit for walking.



Living Streets (The Pedestrians' Association) is a Registered Charity No. 1108448 (England and Wales) and SCO39808 (Scotland). Company Limited by Guarantee (England and Wales), Company Registration No. 5368409. Registered office: 4th Floor, Universal House, 88-94

www.livingstreets.scot

# **Contents page**

- Page 3 Executive Summary
- Page 4 Living Streets Scotland
- Page 4 Introduction
- Page 5 Map of area
- Page 6 Aberfeldy and Area profile
- Page 7 Area findings
- **Page 16 Recommendations**
- Page 18 Action Plan
- Page 20 Contacts
- Page 21 Appendix

### **Executive Summary**

We are Living Streets Scotland, a part of the UK charity for everyday walking. We are working with Perth and Kinross Council road safety team, Councillors, local residents and the Centre for Inclusive Living Perth and Kinross (CILPK) to improve conditions for elderly, mobility and sensory impaired people walking for short, every day journeys in Aberfeldy.

Living Streets has worked with Perth and Kinross Council's Transport Team, undertaking community consultations and street audits previously in Perth, Crieff and Blairgowrie.

We have worked together to record assets and barriers on local streets and paths that encouraged or discouraged everyday walking with the needs of older and more vulnerable pedestrians in mind.

#### Background to Aberfeldy street audit

The Aberfeldy Street Audit follows on from and complements work being carried out by the Aberfeldy Community Council Road Safety Working Group. Information from this sub group and local residents was used to determine an audit route. The main focus of the audit was to look at the accessibility of the town centre and local amenities such as the GP surgery and Dalweem Care Home.

The audit route took in the Coop, Birks Cinema, Post Office, Market Square, Chemist and GP Surgery. Barriers to walking on this route include:

- Lack of dropped kerbs and tactile paving in town centre.
- Poor surfaces on pavements.
- Narrow pavement at pedestrian crossing.
- Poorly maintained pathway to the GP and Care Home.
- Poor sight lines at Zebra Crossing near Market Square and at desired crossing to Coop on Dunkeld Street.

Recommendations for improvements include:

- Improving the dropped kerbs and tactile paving on Moness Terrace and Home Street.
- Improve the pavement surface outside Chillies Indian Restaurant on Dunkeld Street and also on Bank Street between the Premier and the Butchers.
- Widen the pavement at the pedestrian crossing at the Black Watch Inn.

# **Living Streets Scotland**

We are Living Streets Scotland, part of the UK charity for everyday walking. We want to create a walking nation, free from congested roads and pollution, reducing the risk of preventable illness and social isolation and making walking the natural choice. We believe that a walking nation means progress for everyone. Our ambition is to enable people of all generations to enjoy the benefits that this simple act brings and to ensure all our streets are fit for walking.

### Introduction

Living Streets Scotland, LSS, was initially asked to look at the accessibility of Perth Town Centre after some issues were brought to the Transportation team at Perth and Kinross Council by the local Centre for Inclusive Living, CILPK. Their service users highlighted a lack of accessibility especially for those with a mobility or visual impairment. The following year LSS were asked to work with the communities in Crieff and Blairgowrie, looking at the accessibility of routes to local amenities such as Schools, GP surgery and shops.

The street audit work in Aberfeldy follows on from this, with transport officers asking LSS to do community Street Audit work in Kinross, Pitlochry, Aberfeldy, Coupar Angus and a street review in Dunkeld.


The results of this work will help to evidence community priorities and highlight the needs of the most vulnerable pedestrians with the aim of improving access for everyone making short, local journeys on foot.

LSS contacted several local groups and organisations including Out of the Box, Rural Wisdom Project; Aberfeldy Community Council; Vision PK; Community Learning & Development, Perth and Kinross Council; and also local residents. A workshop elicited local information and issues that are barriers to easy movement around Aberfeldy.

The street audit was conducted on 21st February 2018, there were 6 people in attendance for the full length of the route;

- 1 representative from Vision PK
- 1 local CLD officer
- 1 local resident
- 1 representative from the Dalweem Care Home
- 2 representatives from LSS

## Map of area



© OpenStreetMap contributors

The red route indicates the route reviewed

# Aberfeldy & Area profile

The small market town of Aberfeldy is situated in an area of natural beauty in North Perthshire, near to Loch Tay and the Grampian mountains to the North and West. It is at the intersection point of the A826, to Crieff and A827, to the A9 trunk road.

The town has a population of approximately 2000 people, served by amenities in the town that include; supermarket, recently built primary and secondary schools, medical practice, community campus and bank.

There is a busy main road running through Aberfeldy and this brings a high volume of large vehicles through the centre of the town, with traffic dominating parts of the high street. This can be off putting for pedestrians especially at exposed crossing points.

Aberfeldy also provides services to smaller local communities in the area, many of whom use cars to access Aberfeldy as they are unable to use local public transport. This has led to local issues around access to parking in the town, with drivers often double parking or parking on double yellow lines. Parking, and the volume of traffic in the town centre, has implications for road safety for pedestrians accessing amenities.

# **Area findings**

#### What Works Well

There are several areas in the town that encourage walking. The Market Square is an open and inviting space with seating, signage and cycle stands and architectural features. Many of the pavements are wide and there are interesting buildings, cafes and shops.

#### The Market Square

The Market Square is due to be upgraded this year. This will include levelling the surface and removing parking spaces. It is currently a focal point with seating, litterbins and signage.



Seating and signs



Information signs, bike stands and fountain



#### What Doesn't Work So Well

#### 1 – General volume and speed of traffic

As Aberfeldy is at the intersection of two main roads, A826 and A827, there is a high volume of traffic including HGV's. Residents report many of these vehicles are travelling at greater than the town centre 20mph speed limit. This can make pedestrians feel uncomfortable due to close proximity, noise and pollution. This is not helped by the 20mph signs being quite small and placed high up on buildings. It may be worth considering options other than signage to help change driver behaviour, gateway features as drivers enter the town and a change of space allocation to narrow the road. These 'softer indicators can have more of an effect on driver behaviour, helping them to see that they are entering an area with more pedestrians, than just signage.



20mph signs

#### 2 – Zebra Crossing at Birks Cinema

The Zebra crossing is in need of repainting and the lights on the poles could be brighter although it has tactile paving and dropped kerbs. Auditors said that they often preferred not to use this crossing point as it is very close to a mini roundabout and has poor sight lines. The other 2 approaches to the roundabout also have poor sight lines to the Zebra crossing and vehicles often travel at speed approaching the crossing, indicating drivers may not be aware of the facility.



Zebra crossing at Birks Cinema

#### 3 – Desire line crossing to Coop

There is no formal crossing at the Coop on Dunkeld Street. However, many people attempt to cross the road to the Coop as this is a natural desire line. Crossing is difficult due to parked cars blocking sight lines and cars exiting and entering from the Coop and Jet Garage as well as Moness Terrace. The entrance of Moness Terrace leads to the bus stance and there are often large vehicles turning in. Auditors report feeling unsafe crossing at this location due to the dominance of traffic.

One suggestion for improvement was to change the two parking spaces opposite the entrance to disabled spaces. This would hopefully have the effect of these spaces being empty for longer or less likely to have people double park beside them. This would only be effective if disabled parking was enforced.



Dunkeld St at Jet entrance



Carriageway at Moness Terrace

#### 4 – Pedestrian Crossing Kenmore Street and Crieff Road

This junction is a signalised crossing with tactile paving and dropped kerbs. There is no audible signal at the crossing. Residents from the care home say they feel uncomfortable waiting at the corner beside The Black Watch Inn. The pavement is narrow and pedestrians feel exposed and very close to the traffic. This is the main route from the Care Home to the town centre, so should be a priority for improvement.

#### 5 – Obstructions on the pavements

There are several different sections of the pavement that are obstructed and make it difficult for wheelchair and pushchair users to navigate. Some of these obstructions are temporary and others are more permanent.

• Advertising boards on Dunkeld Street and Bridge End. There are advertising boards placed around the town centre, these pose an obstruction to more vulnerable pedestrians.



Advertising boards on Dunkeld St

• Wheelie bins and railings at the Chemist on Bridge End. The combination of poorly placed wheelie bins and the railings can be an obstruction, especially to less mobile pedestrians using the Chemist.



Wheelie bins at Chemist

• Split level raised kerbs on the Market Square and Bank Street. There is little contrast between the pavement and the raised kerb and this poses a potential trip hazard for the visually impaired, and this is increased if there are multi-level kerbs.



Split kerbs on Market Square and Bank St

• Narrowing of the pavement at the corner of The Breadalbane Arms. The narrow corner and pavement is on a corner with poor sight lines. This is an intimidating space with close proximity to busy main road. There is space to allow the footway to be widened at this corner.



Narrow footway at Breadalbane Arms

• On Market Square, there is a pole for hanging baskets, and this is also where the Christmas tree is situated. The area around the pole has bevelled edges that are used as drainage channels. There is no real contrast in colour between the flat and bevelled paving making this a trip hazard for the visually and mobility impaired.



Drainage channels in Market Square

#### 6 – Pavement maintenance

There are several areas along the route that are poorly maintained, making walking difficult for vulnerable pedestrians. Several areas were highlighted by the care home residents as uncomfortable or impossible to traverse in a wheelchair.

• Pavement near entrance to Coop on Dunkeld Street. The surface is very broken up and uneven. This surface, along with vehicles crossing to enter the Garage or Coop, makes it a difficult space for vulnerable pedestrians.



Footway at Coop entrance on Dunkeld Street

 Pavement in front of Chillies Indian Restaurant. Although this area has double yellow lines, there are often vehicles parked on the pavement, while drivers and passengers visit the restaurant. Auditors reported that there were sometimes tractors parked here. This has exacerbated the breakup of the pavement surface. Pavement parking, and the poor condition of the pavement surface in this location make this a difficult space for vulnerable pedestrians.



Footway at Chillies Restaurant, Dunkeld St

• Bank Street between the Butchers and the Premier Store. Residents of the Care Home have shared that this is a difficult section of pavement to traverse, especially in a wheelchair.



Footway at Bank St, between Butcher and Premier Store

• Entrance path to the park and route to Birks of Aberfeldy. The entrance path is very broken up and steep. Care Home residents do not feel able to access this entrance; staff do not feel able to push residents in wheelchairs up or down the incline.



Entrance path to Birks of Aberfeldy

 Narrow pavement on bridge on Bank Street. The pavement surface is poorly maintained and a trip hazard for vulnerable pedestrians.



Narrow footway on bridge on Bank St

• Lack of dropped kerb at junction of Dunkeld Street and Home Street, this leads to a long detour for Wheelchair and mobility scooter users.



No dropped kerb at Home St and Dunkeld St junction

 Path to GP Surgery and Care Home from Kenmore Street opposite the Police Station. This short path leading to the GP Surgery and Dalweem Care Home is a popular route from the town centre. The route via the main roads from Care Home and GP Surgery is much longer. The short path is badly maintained and in the evenings very dark. Staff reported that in the evenings they have to use a torch to navigate the path. The path is bordered by several homes and at times there are vehicles parked on the path, these can block the path so that wheelchairs cannot access.



Path to GP and Care Home from Kenmore St

#### 7 – Enforcement of double yellow lines

There are often vehicles parked on the double yellow lines on the Square, many of these are delivering goods to local businesses. Whilst on the audit it was also noted that the mobile bank was parked on Dunkeld Street close to the junction with Home Street.



Double yellow line parking, Market Square and Dunkeld St

#### 8 – Space allocation

On Dunkeld Street from the Spar to Pets Etc there is a stretch of pavement that at each corner, if walking in a straight line, turns into parking spaces. This is a confusing space and there is little demarcation between pavement and the road. This is a difficult space to navigate for pedestrians and especially the visually impaired.



Confusing parking layout on Dunkeld St

### Recommendations

Area/Issue	Recommended Action	Level of Action Quick Win/ Iong Term	Responsibility/ Involvement
1 - Obstructions	<ul> <li>1 – Advertising Boards in the town centre, ensure that business owners are aware of regulations and these are enforced.</li> <li>2 – Wheelie bins in the town centre, work with business owners and PKC staff to leave pavements unobstructed.</li> <li>3 – Raised kerbs in the Market Square and on Bank Street, paint the edges of the raised kerbs to be as visible as possible to visually impaired. (this may be resolved as part of the Market Square upgrade).</li> <li>4 – Drainage channels in the Market Square, (this may be resolved as part of the Market Square upgrade).</li> </ul>	1 – Quick win 2 – Quick win 3 – Quick win 4 – Quick win	РКС
2 – Footway Surfaces (maintenance)	<ul> <li>1 – Pavement at Coop on Dunkeld Street, repair the surface.</li> <li>2 – Pavement at Chillies Restaurant on Dunkeld Street, repair the surface</li> <li>3 – Bank Street, between Butcher and Premier, repair the surface</li> <li>4 – Bank Street, narrow pavement, repair the surface</li> <li>5 – Entrance to park to Birks of Aberfeldy, reduce the incline to the entrance and repair the surface</li> <li>6 – Path to GP Surgery, resurface the path and add lighting</li> </ul>	1 – Quick win 2 – Quick win 3 – Quick win 4 – Quick win 5 – Long term 6 – Long term	PKC, home owners adjacent to the path to the GP Surgery, Aberfeldy Community Council
3 – Footway Surfaces (dropped kerbs)	1 – Junction of Dunkeld Street and Home Street, install a dropped kerb at the crossing points.	1 – Quick win	РКС

Area/Issue	Recommended Action		Responsibility/ Involvement
4 – Crossing Points	<ul> <li>1 – Zebra crossing needs to be repainted as it is fading.</li> <li>2 – Replace the parking spaces on each side of the 'Keep Clear' sign on Dunkeld Road opposite the entrance to Moness Terrace with disabled parking bays.</li> <li>3 – Pedestrian crossing beside Black Watch Inn, extend the footway to create more space for waiting pedestrians.</li> </ul>	1 – Quick win 2 – Quick win 3 – Long term	РКС
5 – Traffic	1-20 mph roundels to be painted on the roads through the town centre.	1 – Long term	РКС
6 – Space Allocation	1 – Remove these dangerous parking spaces or make some demarcation for visually impaired pedestrians to know they are not on the footway.	1 – Long term	РКС

### **Action Plan**

Action	Responsibility
Advertising Boards in the town centre, ensure that business owners are aware of regulations and these are enforced.	PKC Roads team
Wheelie bins in the town centre, work with business owners and PKC staff to leave pavements unobstructed.	PKC Roads team
Raised kerbs in the Market Square and on Bank Street, paint the edges of the raised kerbs to be as visible as possible to visually impaired. (this may be resolved as part of the Market Square upgrade).	PKC Roads team
Drainage channels in the Market Square around the area used for the Christmas tree, (this may be resolved as part of the Market Square upgrade).	PKC Roads team
Pavement at Coop entrance on Dunkeld Street, repair the surface.	PKC Roads team
Pavement at Chillies Restaurant on Dunkeld Street, repair the surface	PKC Roads team
Bank Street, between Butcher and Premier, repair the surface	PKC Roads team
Bank Street, narrow pavement, repair the surface	PKC Roads team
Entrance to park to Birks of Aberfeldy, repair the entrance surface from road to park gates and install hand rail. (possible Community Links Funding)	PKC Roads team
Path to GP Surgery, resurface the path and add lighting	PKC Roads team, Community Council,
- Identify group to take this project forward.	homeowners adjacent to path.
- Identify who owns/has responsibility for the path and feasibility of upgrading surface and adding lights.	
Junction of Dunkeld Street and Home Street, install a dropped kerb at the crossing points	PKC Roads team
Zebra crossing needs to be repainted as it is fading.	PKC Roads team and Transport Scotland
Replace the parking spaces on each side of the 'Keep Clear' sign on Dunkeld Road opposite the entrance	PKC Roads team and Transport
to Moness Terrace with disabled parking bays.	Scotland

Action	Responsibility
Pedestrian crossing beside Black Watch Inn, extend the footway to create more space for waiting pedestrians.	PKC Roads Team
20 mph roundels to be painted on the roads through the town centre.	PKC Roads team and Transport Scotland
Remove these dangerous parking spaces or make some demarcation for visually impaired pedestrians to know they are not on the footway.	PKC Roads team and Transport Scotland

### **Contacts**

This report is being submitted to:

- Perth and Kinross Council Traffic and Network team
- Aberfeldy Community Council
- Centre for inclusive living Perth and Kinross

Contacts:

Avril McKenzie, Living Streets Scotland avril.mckenzie@livingstreets.org.uk

# Appendix

Community Street Audit Findings

Map Ref	Location	Findings	Effect on walking	Heading	Priority/solution
	Zebra crossing outside Birks Cinema	Poor sight lines, too near to mini roundabout	Difficult to cross, hard to see oncoming traffic and speeding traffic, from connecting roads. Intimidating for pedestrians	Crossing points and desire lines	Repainting Zebra crossing, increasing lights on poles. Long term would be possible to re- site on Chapel Street as has better site lines or have Zebra on all 3 roads (Chapel St, Dunkeld St and The Square.

Map Ref	Location	Findings	Effect on walking	Heading	Priority/solution
	Location Dunkeld St between Birks Cinema and Coop	Various A boards	Partial blocking of footway	Footway surfaces and obstructions	Removal of A boards or re- siting them close to wall side of footway.

Map Ref	Location	Findings	Effect on walking	Heading	Priority/solution
	Dunkeld St between Birks Cinema and Coop	Various A boards	Partial blocking of footway	Footway surfaces and obstructions	Removal of A boards or re- siting them close to wall side of footway.
	Dunkeld Street between Spar and Pets ETC	Footway morphs into parking spaces as shops in this block are set back slightly from the rest of the buildings on the street. There are driveways at each end of the block with raised level to footway.	This is very confusing and possibly dangerous, especially confusing for visually impaired as there is nothing to differentiate the footway, access road and parking spaces.	Road layout and space allocation	Paint some markings on the footway/parking spaces to show where they each start/stop.

Map Ref	Location	Findings	Effect on walking	Heading	Priority/solution
	Coop on Dunkeld St	The Coop and Jet garage share the same entrance and exit points. There is a no entry sign at the exit point, the no entry sign is parallel to road and difficult for drivers to see until they commit to make a turn. Both the entrance and exit points are across the pavement	Traversing pavement can be dangerous if cars turn in here unexpectedly.	Facilities and signage, rod layout and space allocation	Re-site the no entry sign to be more visible to drivers. Paint markings on the pavement to highlight entrance/exit.
	Dunkeld St in front of Coop/garage	Footway in need of maintenance	Tip hazard for people with reduced mobility	Footway surfaces and obstructions	Resurface footway

Location Crossing Moness Terrace	<b>Findings</b> Lack of dropped kerbs and footway and carriageway poorly maintained	Effect on walking Pedestrians with poor mobility will find this difficult to cross	Heading Footway surfaces and obstructions	<b>Priority/solution</b> Add dropped kerbs and repair the footway and carriageway. Remove 2 parking bays opposite Moness Terrace to allow for easier bus access to depot and improve sight lines
Dunkeld Street/Home Street corner	Parking on double yellow lines. Lack of dropped kerbs on Home Street corner	Blocks site lines and crossing points. Mobility scooter and wheelchair users will have to go on road to cross junction due to lack of dropped kerbs	Maintenance and enforcement issues Crossing points and desire lines	Enforce parking restrictions Addition of dropped kerbs

Map Ref	Location	Findings	Effect on walking	Heading	Priority/solution
	Outside Chillies Indian Takeaway	Pavement damaged by people parking on it at DYL	Pedestrians with poor mobility will find this difficult to traverse	Maintenance and enforcement issues	Enforce parking restrictions, bollards to stop pavement parking
	Mini roundabout on the Square	3 roads lead to roundabout, a lot of HGV's using the road. Feels quite intimidating and traffic often approaches it above the 20mph limit.	Intimidating to cross any of the approach roads to and from the Market Square.	Maintenance and enforcement	Highlight the 20mph speed limit better, small signs on approaches high on buildiings – maybe paint 20mph roundel on road surface

Map Ref	Location	Findings	Effect on walking	Heading	Priority/solution
	Seating and Signs in the Market Square	The square is to be upgraded and made more pedestrian friendly, on a single level and losing parking spaces. There is seating and signage. The cycle maps and racks are good but it may be useful to have a more local map on one side of the double sided sign. Would be good to have either distance or walking times on the finger signs.	Pleasant area to be in with shops and decorative architecture.	Facilities and signage, Aesthetics	Add information to the signs as detailed.

Map Ref	Location	Findings	Effect on walking	Heading	Priority/solution
	Feature in the Square outside Habitat Café	This pole has flower baskets in the summer and is replaced by a tree at Christmas time. The pole area is surrounded by a shallow drain area.	The shallow drain is a trip hazard for visually impaired or pedestrians with mobility issues as it is the same colour as the rest of the paving	Footway surfaces and obstructions	Level off the area or at least have this in a contrasting colour to make it obvious to pedestrians (this may be changed as part of the Market Square upgrade)

Map Ref	Location	Findings	Effect on walking	Heading	<b>Priority/solution</b>
	Fountain	Area of interest, would be good to have this back to working order	Something to look at in the square	Aesthetics	Fix the fountain to flow again
	Corner from Square to Bridge End	Split level kerb on the curve.	This could be a trip hazard as it is not easily seen as it is the same colour as the pavement	Footway surface and obstructions	Either have single level kerb but would be better to have contrasting colour.

Map Ref	Location	Findings	Effect on walking	Heading	Priority/solution
	Breadalbane	Double Yellow Lines	Blocks road and	neading	Enforce double
	Arms Hotel	around the hotel are often	makes it difficult to		yellow lines.
		ignored.	cross.		,
					Widen pavement
		At the Bridge end of the	Difficult to travel on		
		building there is a narrow	this side of the road		
		kerb.	as close to traffic on		
			a corner/bend.		Add dropped
		At the Market Square end	Hard for wheelchair		kerb – this may
		of the building there is no	users to cross on		be done as part
		dropped kerb to Market	to/from Square		of the levelling of
NT2A		Square			the square
					upgrades
			Blocks road and		
			makes it difficult to		Enforce double
	Breadalbane	Double Yellow Lines	cross.		yellow lines.
	Arms Hotel	around the hotel are often			
Perdie à Boo		ignored.	Difficult to travel on		Widen pavement
			this side of the road		
		At the Bridge end of the	as close to traffic on		
Contraction of the second s		building there is a narrow	a corner/bend.		
		kerb.	Hard for wheelchair		Add dropped
			users to cross on		kerb – this may
		At the Market Square end	to/from Square		be done as part
		of the building there is no			of the levelling of
		dropped kerb to Market			the square
		Square	1		upgrades

Man Def	Location	Findings		llooding	
<image/>	Park Entrance on Bridge End	Findings Steep incline and badly maintained footpath	Effect on walking This is inaccessible if you have any mobility issues or are a wheelchair user.	Heading Footway surfaces and obstructions	Priority/solution Resurface footpath, possibly level out incline add a handrail.
	Bridge on Bank Street	Footway on the left heading to Kenmore St is narrower than the one on the right. Almost single file on left. The surface is poorly maintained	Hard to navigate if you use a mobility aid or are less mobile	Road layout and space allocation Footway surfaces and obstructions	Resurface the footway

Map Ref	Location	Findings	Effect on walking	Heading	Priority/solution
	Bank Street, outside Chemist	There are railings and a dropped kerb outside the chemist and several bins nearby	Can obstruct pedestrians	Footway surfaces and obstructions	Ensure bins are kept up against the wall as far from railings as possible
	Bank Street between Premier and butcher	Poorly maintained footpath	Trip hazard for pedestrians with poor mobility	Footway surfaces and obstructions	Resurface footway

Map Ref	Location	Findings	Effect on walking	Heading	Priority/solution
	Bank Street between Premier and butcher	Poorly maintained footpath	Trip hazard for pedestrians with poor mobility	Footway surfaces and obstructions	Resurface footway

		<b></b>			
Map Ref	Location	Findings	Effect on walking	Heading	Priority/solution
	Railings outside	Narrows the footway at	Can cause an	Footway surfaces	
	the Blackwatch	the corner	obstruction at the	and obstructions	
	Inn at the corner		corner, but does offer a barrier from		
			fast traffic		
154 15					
4	Junction between	Crossing points have	Residents and staff	Crossing points	Widen corner
	Kenmore St,	dropped kerbs, corner at	from Dalweem Care	and desire lines	footway at The
	Taybridge Road,	Blackwatch Inn narrow.	Home find it		, Black watch Inn
	and Bank Street		intimidating to wait		
			for lights here due		
			to close proximity		
-			with traffic		
-					

Map Ref	Location	Findings	Effect on walking	Heading	Priority/solution
	Taybridge Road	Footway stops on one side half way	Pedestrians need to cross at the crossing to ensure easy access down Taybridge Road	Footway surfaces and obstructions	

		<b></b>			
Map Ref	Location General from	Findings	Effect on walking Traffic feels	Heading	Priority/solution
	Kenmore Street	Lots of parking on double yellow lines and speeding	dominant in this	Maintenance and enforcement	Enforce the 20mph speed
	to Bridge End	traffic in the area.	area. Can be an	emorcement	limit and double
		There are often HGV's	intimidating space		yellow lines
		parked on the corner	with loud, fast		
		exiting the Square near	traffic		
1/2		the fountain.			
Part Part					
<u> </u>					
t fil					
THE WAR LEVE		Lots of parking on double			
and the second sec	General from	yellow lines and speeding	Traffic feels	Maintenance and	Enforce the
	Kenmore Street	traffic in the area.	dominant in this	enforcement	20mph speed
	to Bridge End	There are often HGV's	area. Can be an		limit and double
		parked on the corner	intimidating space		yellow lines
		exiting the Square near	with loud, fast		
		the fountain.	traffic		

Man Def	Location	Findings	Effect on welking	Uppding	Driesity/colution
	Location Lane off Kenmore Street opposite the Police Station, to the GP surgery and Dalweem care Home	Findings This lane has a badly maintained footway surface and is sometimes blocked by a resident's car. There is no lighting along this lane.	Effect on walking This lane is often used to get to and from the GP and Care home and is the preferred route to take residents in to town as it is shorter than going by Taybridge Rd. Lane is sometimes blocked by a car so that wheelchairs can't pass through	Heading Maintenance and obstructions, Personal safety	Priority/solution Resurface lane, add lighting There is doubt about who owns the land and several people may be involved in agreeing any changes.

Map Ref	Location	Findings	Effect on walking	Heading	Priority/solution
	Lane off Kenmore Street opposite the Police Station, to the GP surgery and Dalweem care Home	This lane has a badly maintained footway surface and is sometimes blocked by a resident's car. There is no lighting along this lane.	This lane is often used to get to and from the GP and Care home and is the preferred route to take residents in to town as it is shorter than going by Taybridge Rd. Lane is sometimes blocked by a car so that wheelchairs can't pass through	Maintenance and obstructions, Personal safety	Resurface lane, add lighting There is doubt about who owns the land and several people may be involved in agreeing any changes.



#### For more information contact Living Streets Scotland

Thorn House 5 Rose Street Edinburgh EH2 2PR

Telephone: 0131 243 2645 Email: Scotland@livingstreets.org.uk

#### In association with



Funded by

